Waterproofing – Horizontal Hebel Surfaces

Products required
- **MAXSEAL FLEX "M"**
- **MAXSEAL TRAFFIC**

Method
1. Remove all render, paint or other material from the substrate.
2. Surface to be coated must be primed with a coat of **MAXSEAL FLEX M** mixed to a slurry (2 parts powder to 1 part water). This will seal the surface in preparation for finish coats. Surface must be wet before applying prime coat.
3. Leave to cure overnight.
4. Final coat **MAXSEAL FLEX M** Apply one coat of 1 kg/m2 over the primed surface.
5. Remember to leave overnight between coats of primer coat and **MAXSEAL FLEX M**. Also remember to dampen surface prior to application of coats.
6. Leave for 4-5 days to cure.
7. After this time the surface can be tiled, rendered or painted as required.

FOR TRAFFICABLE SURFACES:

Apply 2 coats of MAXSEAL TRAFFIC after steps 1 to 3 above.